



Abmessungen

x = Anzahl der Bohrungen

Ø Da [mm]	Ø D1 [mm]	Ø D2 [mm]	Ø DA [mm]	Ø LK [mm]	x	L1 [mm]	s [mm]	Ø B [mm]
75	69	84	140	110	8	29	6,5	10
90	84	98	158	128	8	29	6,5	10
110	106	116	170	150	8	30	8,0	10
125	122	131	185	165	8	30	8,0	10
140	136	146	200	175	8	30	8,0	10
160	156	166	230	200	8	30	8,0	10
180	166	186	245	220	8	30	8,0	10
200	196	206	270	240	8	30	8,0	10
225	222	231	290	265	8	30	8,0	10
250	246	256	320	290	12	30	8,0	10
280	275	287	355	325	12	30	10,0	10
315	310	322	380	350	12	30	10,0	10
355	349	362	435	400	12	30	10,0	10
400	393	408	475	445	12	30	10,0	10

Weitere Abmessungen auf Anfrage